Assessment Check List

Parcel ID#	Damage Address	City	Zip Code								
EF-291-AQ	590 FIRE ISLAND AVE	BABYLON	11702								
		Yes	No								
	Provide Site Signage	Х]							
	Maintain Landscaping	Yes	No	Current	Condition	Norma	High X	Good	Bad X	1	
	Maintain Lanuscaping	^	<u> </u>	J			^	<u> </u>	^	J	
		Yes	No	Hand	Yes	No	Machine	Yes	No	Both	
	Clean Out Debris	Χ								Х	
		Yes	No								
	Install Fencing	X	INO	1							
	.			J							
		Yes	No	Front	Left	Rear	Right	All			
	Board Up Doors/Windows	Х			Х	Х	Х		J		
		Gas	On	Off	Electric	On	Off	Oil	Yes	No	
	Verify Status of Utilities	500	Х			Х					
					_			•			
	Miscellaneous Site Work	Notes:									
	Wiscenarieous Site Work	notes.	J								
	Remove Standing Water	Standing Water		Yes	No						
	Drainage Issues	Standing W	atei	163	X	1					
	C	Drainage Issues		Yes	No	.					
					Х						
	Pest/Vermin Control	Roaches	Bats	Rats	Other: Ex	nlain					
	1 CSG VETTILLI COLLUDI	X	Dats	X	Julei. EX	Piairi	1				
							_				
	Structural Integrity	Good	Bad	Demolis	h T						
		Х			J						

Habitable with Minor Clean up

Yes No

Hazardous/ Environmental Material Abatement Notes: Neigbhors stated that they have seen a number of rats coming from the property.

Verify Status of Bulkheads

Yes No

x Decking appears to damaged and weathered.

Provide Security Personnel

Yes No

Notes:

Neighbors stated that the occupant just move out 7/1/2014 at the time of inspection the front porch light was on and the utilities appear to be on.

In addition a number of rats have been seen coming from the back yard of the property according to the neighbors.

1 Front

Date Taken: 7/14/2014 Taken By: MGREEN



2 Street LeftDate Taken: 7/14/2014Taken By: MGREEN



3 Street Right
Date Taken: 7/14/2014
Taken By: MGREEN



4 Address
Date Taken: 7/14/2014
Taken By: MGREEN



5 Front-Elevation
Date Taken: 7/14/2014
Taken By: MGREEN



6 Front-Elevation
Date Taken: 7/14/2014
Taken By: MGREEN



7 Left-Elevation
Date Taken: 7/14/2014
Taken By: MGREEN
Overgrown vegetation



Left-Elevation
 Date Taken: 7/14/2014
 Taken By: MGREEN

 Electric utilities are still connected.



9 Left-Elevation Date Taken: 7/14/2014 Taken By: MGREEN

Gas meter is connected.



10 Left-Elevation
Date Taken: 7/14/2014
Taken By: MGREEN

Siding does not appear to be damage.



11 Left-Elevation
Date Taken: 7/14/2014
Taken By: MGREEN



12 Left-Elevation
Date Taken: 7/14/2014
Taken By: MGREEN

Back to front view of left elevation.



13 Rear-Elevation
Date Taken: 7/14/2014
Taken By: MGREEN

Overall view of the rear elevation.



14 Rear-Elevation
Date Taken: 7/14/2014
Taken By: MGREEN

Overall view of the rear elevation.



Rear-YardDate Taken: 7/14/2014Taken By: MGREENIs overgrown with vegetation.



Rear-YardDate Taken: 7/14/2014Taken By: MGREENIs overgrown with vegetation.



17 Rear-Yard
Date Taken: 7/14/2014
Taken By: MGREEN

Is overgrown with vegetation.



18 Right-Elevation
Date Taken: 7/14/2014
Taken By: MGREEN



19 Right-Elevation
Date Taken: 7/14/2014
Taken By: MGREEN

Right elevation shows no damage.



20 Right-Elevation
Date Taken: 7/14/2014
Taken By: MGREEN
Storage unit has no damage.



21 Right-Elevation
Date Taken: 7/14/2014

Taken By: MGREEN

Back to front view of overgrown vegetation on the right side of the house.



22 Right-Elevation
Date Taken: 7/14/2014
Taken By: MGREEN

Back to front view of overgrown vegetation on the right side of the house.



23 Roof

Date Taken: 7/14/2014 Taken By: MGREEN

No damage observed at the time of assessment.



24 Roof

Date Taken: 7/14/2014 Taken By: MGREEN



25 Bulkhead Date Taken: 7/14/2014 Taken By: MGREEN



26 Bulkhead
Date Taken: 7/14/2014
Taken By: MGREEN

